


CORNER RECORD

Agency Index BK. 21 Pg 60Document Number 20190013City of ROSEVILLE County of PLACER, CaliforniaBrief Legal Description CENTERLINE MONUMENT SIERRA GARDENS DRIVE PER 29-PM-83

CORNER TYPE



- ☐ Government Corner ☐ Control
☐ Meander ☐ Property
☐ Rancho ☒ Other

Date of Survey July 23, 2018

S.1. T.10N. R.06E.

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units ☐ Metric ☒ U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902

PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:

Corner/
Monument: ☒ Left as found ☐ Established ☐ Rebuilt ☒ Pre-Construction
☐ Found and tagged ☐ Reestablished ☒ Referenced ☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet #2 for description(s):

Found 3/4" rebar without tag on the centerline of Sierra Gardens Drive at the westerly BC per 29-PM-83.
Set lead and brass tag reference points in top of curb as shown on sheet 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on August 15, 2018Signed [Signature] P.L.S. or R.C.E. No. 7953

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed April 30, 2019Signed [Signature] P.L.S. or R.C.E. No. 6584Title County Surveyor

County Surveyor's Comment _____



BOOK 21 OF CORNER RECORDS, PAGE 60

LEGEND

- ✕ SET LEAD & BRASS TAG IN CONCRETE STAMPED PLS 7953 AS A REFERENCE POINT
- FOUND 3/4" REBAR AT BC PER 29-PM-83
- ✕ FOUND REBAR AS NOTED
- == CURB & GUTTER

NOTES

1. THE LOCATION OF FOUND MONUMENTS HAS NOT BEEN SURVEYED IN RELATION TO RECORD MAPS.
2. THE REFERENCE POINTS SHOWN HEREON WERE SET IN ORDER TO PRESERVE THE AS-FOUND LOCATION OF THE MONUMENT PRIOR TO ROAD CONSTRUCTION.

NOT TO SCALE

BOOK 21 OF CORNER RECORDS, PAGE 60

